Division of Health Service Regulation

(X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING: 01 B. WING HAL051041 09/30/2016 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 145 DAIRY ROAD **CLAYTON HOUSE** CLAYTON, NC 27520 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETE (EACH CORRECTIVE ACTION SHOULD BE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PRÉFIX PREFIX DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) C 000 Initial Comments C 000 Report of a Biennial Construction Survey by Frank Strickland and Billy Bryant on 09/30/2016: This facility was first licensed on 03/15/1985. The facility is licensed for 60 beds. Therefore, this facility was surveyed for conformance with the 1978 edition of the North Carolina State Building Code, the 1984 Homes for the Aged and Infirm Minimum Desired Standards and Regulations and the applicable portions of the 2005 Rules for Adult Care Homes of Seven or More Beds. Deficiencies were cited and a Plan of Correction is required. C 148 C 148 Corridors-Handrails SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL **ENVIRONMENT** (g) The requirements for corridors are: (2) Handrails shall be provided on both sides of corridors at 36 inches above the floor and be capable of supporting a 250 pound concentrated load; This Rule is not met as evidenced by: 1-Based on observations, this facility has failed to maintain the corridor handrails. This may affect residents. Findings on 09/30/2016: The handrails are unfastened to the corridor walls at the following locations: (a) Outside Room 108 (b) Mechanical Room/100 Hall (c) Outside Room 211

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01		(X3) DATE SURVEY COMPLETED		
		HAL051041	B. WING		09/3	0/2016	
			DRESS, CITY, S	STATE, ZIP CODE			
CL AVTO	CLAYTON HOUSE 145 DAIRY ROAD						
OLATIO	N 11000E	CLAYTON	, NC 27520				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROF	OULD BE COMPLETE		
C 160	Continued From pa	ge 1	C 160				
C 160	Outside Premises-Clean, Safe		C 160				
	(1) The outside grofacilities shall be macondition; This Rule is not median 1-Based on observation affect residents and Findings on 09/30/2 The outside ground following hazards: (a) Abandoned statillot, (b) Pile of cut-up tree (c) Bed mattresses the rear of the facilities.	onts for outside premises are: bunds of new and existing aintained in a clean and safe et as evidenced by: ations, this facility has failed to dis free of hazards. This could a staff. consumer the front parking the limps in front of the facility, leanng against dumpsters at					
C 164	Housekeeping and	Furnishings-Clean, Repaired	C 164				
	coverings kept clea (2) have no chronic (3) have furniture c	es shall: ings, and floors or floor n and in good repair;					

Division of Health Service Regulation

facilities.

STATE FORM 6899 EBOP21 If continuation sheet 2 of 7

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING: 01 B. WING _ HAL051041 09/30/2016 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 145 DAIRY ROAD **CLAYTON HOUSE** CLAYTON, NC 27520 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE DATE (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) C 164 Continued From page 2 C 164 This Rule is not met as evidenced by: 1-Based on observations, this facility has not maintained the ceiling construction. This could affect residents and staff while occupying spaces with this condition. Findings on 09/30/2016: The ceiling has become unfastened to supporting structure along with the privacy curtain track in the Women's Bath. 2-Based on observations, this facility has not maintained the plumbing fixtures. This will affect the residents. Findings on 09/30/2016: The toilet is out of order in the Women's Bathroom. 3-Based on observations, this facility has not maintained the wall construction. . Findings on 09/29/2016: The corridor walls need sheet-rock repair and a finish. 4-Based on observations, this facility has not maintained the ceiling construction. This could affect residents and staff while occupying spaces with this condition. Findings on 09/30/2016: The ceiling is damaged due to water leak from the attic in the Staff Break Room. 5-Based on observations, this facility has not maintained the prevention of water migration through exterior walls.

Division of Health Service Regulation

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING: 01 B. WING _ HAL051041 09/30/2016 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 145 DAIRY ROAD **CLAYTON HOUSE** CLAYTON, NC 27520 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX PREFIX DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) C 164 Continued From page 3 C 164 Findings on 09/30/2016: The AC unit that is mounted at the base of the exterior wall in the Staff Break Room does not have any preventative measures in place to prevent water migration. 6-Based on observations, this facility has not maintained the interior door hardware. Findings on 09/29/2016: The following interior doors have damaged hardware that prevents the doors to latch: (a) Room 107 C 189 Building Equipment Maintained Safe, Operating C 189 SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1-Based on observations, this facility has failed to maintain the active fire protection devices. Findings on 09/30/2016: There was not a fire extinguisher in the cabinet located at the end of the front left-hand side Hall. 2-Based on observation, this facility has failed to maintained in a safe and operating condition the

Division of Health Service Regulation

emergency lighting. This would affect all

STATE FORM 6899 EBOP21 If continuation sheet 4 of 7

Division of Health Service Regulation								
STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPL		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01		(X3) DATE SURVEY COMPLETED			
HAL051041		B. WING		09/30/2016				
NAME OF I	PROVIDER OR SUPPLIER	STREET ADI	DRESS, CITY, S	STATE, ZIP CODE				
CLAYTON HOUSE 145 DAIRY CLAYTON,		Y ROAD N, NC 27520						
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROPERTION OF T	D BE	(X5) COMPLETE DATE		
C 189	Continued From page 4		C 189					
	residents, staff and visitors if the egress pathways were not illuminated during a power outage.							
	located at the follow	ency wall lights that are ving locations did not ted in the emergency mode:) Hall						
	3-Based on observations, this facility has failed to provide life-safety devices to activate the fire alarm control panel in the event of an emergency. This will affect all residents, staff and guests.							
	Findings on 09/30/2 One of the required does not have a ma	exit doors in the Dining Room						
	maintain the outbuil	ations, this facility has failed to Idings on site in a safe nazard to the residents and						
		2016: ing at the rear yard of the ' hole in the froof and is about						
	maintain the smoke	ations, this facility has failed to e-barrier door hardware. This its and staff in an event of an uate the facility.						
	Findings on 09/29/2 The cross-corridor	2016: doors that are located						

Division of Health Service Regulation

adjacent to Room 103 do not latch.

STATE FORM 6899 If continuation sheet 5 of 7 EBOP21

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES		(X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CONSTRUCTION		(X3) DATE SURVEY	
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER:	A. BUILDING: 01		COMPLETED	
		HAL051041	B. WING		09/3	0/2016
NAME OF PROVIDER OR SUPPLIER STREET ADD		DRESS, CITY, S	STATE, ZIP CODE			
CLAYTO	N HOUSE	145 DAIR	_			
(VA) ID	CLIMMA DV CTA	TEMENT OF DEFICIENCIES	, NC 27520	PROVIDER'S PLAN OF CORRECTION		(VE)
(X4) ID PREFIX TAG	(EACH DEFICIENCY	'MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	(EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROI DEFICIENCY)	.D BE	(X5) COMPLETE DATE
C 189	Continued From page 5		C 189			
	maintained the woo	ations, this facility has not dramp construction at the This is a hazard to residents,				
	Findings on 09/29/2016: The rear HC wood ramp has the following degrading components: (a) Rooten wood decking (b) Handrails that are spitting leaving obstructions (c) Handdrails wilh exposed nails at gripping surfaces (d) Ramp surfaces that are not anti-slip					
	maintained in a safe of oxygen cyclinder residents and staff	ation, the facility has not e manner by improper storage s. This could affect all by potentially exposing them tured ruptured cyclinder.				
	Findings on 09/30/2 There are oxygen I racks in the Med Ro	oottles not stored in approved				
C 199	Exhaust Ventilation		C 199			
	provided with exhautwo cubic feet per n requirement does n	ed in this Paragraph shall be ust ventilation at the rate of ninute per square foot. This ot apply to facilities licensed with natural ventilation in ces:				

Division of Health Service Regulation

STATE FORM 6899 EBOP21 If continuation sheet 6 of 7

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01		(X3) DATE SURVEY COMPLETED	
		HAL051041	B. WING		09/3	30/2016
NAME OF PROVIDER OR SUPPLIER CLAYTON HOUSE STREET ADD 145 DAIRY CLAYTON,				STATE, ZIP CODE		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES 'MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APPR DEFICIENCY)	ULD BE	(X5) COMPLETE DATE
C 199	(4) housekeeping of (5) laundry area. (k) This Rule shall facilities with the ex which shall not app. This Rule is not me 1-Based on observe provide an environmalle by not providing generated. This couby subjecting them	apply to new and existing ception of Paragraph (e) ly to existing facilities. et as evidenced by: ation, this facility failed to ment in accordance with this no ventilation where odors are all affect residents and staff to house-keeping odors.	C 199			

6899

Division of Health Service Regulation STATE FORM